








8x
5-500



2x
390010190



8x
5,0-60SU



2x/4x
190311513

1

A



4x
5-500

B




2x
390010190


C



4x
5,0-60SU




1




2




3




4






2




3




4




5A




5B






6




7




8





9A





9B




10A




10B




11




12




13




14




14A





14B



14C



15



Dansani A/S
Finlandsvej 8
DK-6100 Haderslev
Tel.: +45 73 22 29 00
Mail: mail@dansani.dk

www.dansani.com www.scanbad.com



No. 1473 250107 Rev. 01